

PHILIPS

Automated
External Defibrillator



Be prepared for a surge in cardiac arrests related to COVID-19

The Philips HeartStart OnSite and HeartStart FRx AEDs

As quarantine orders are lifted and Americans head back to work, Philips is focused on protecting community members who may have leftover heart damage caused by COVID-19.^{1,2} Having a Philips HeartStart OnSite or HeartStart FRx AED at your place of work can give an added peace of mind for people with compromised hearts.



78%

of people diagnosed with COVID-19 showed evidence of heart damage caused by the disease weeks after they have recovered.³



Cardiac complications

of COVID-19 are equal to those of SARS, MERS and influenza.⁵



44.4%

of ICU patients in Wuhan, China, hospitalized with COVID-19, experienced arrhythmia.⁴



Arrhythmia is a top 3 risk

of viral infections.⁴ People with COVID-19, SARS, MERS and influenza⁵ are at a major risk for arrhythmias (heartbeats that are too fast, slow or irregular).

The Philips HeartStart OnSite and HeartStart FRx AEDs

Help protect your employees, co-workers, customers, clients and community members with a Philips HeartStart OnSite or HeartStart FRx AED.

Visit www.philips.com/AEDs for more information on the HeartStart OnSite and HeartStart FRx AEDs.



References

1. Post W. Heart problems after COVID-19. <https://www.hopkinsmedicine.org/health/conditions-and-diseases/coronavirus/heart-problems-after-covid19>. Accessed August 24, 2021.
2. Bhatla A, Mayer MM, Adusumalli S, et al. COVID-19 and cardiac arrhythmias. *Heart Rhythm*. 2020. DOI: <https://doi.org/10.1016/j.hrthm.2020.06.016>.
3. Puntmann VO, Carerj ML, Wieters I, et al. Outcomes of cardiovascular magnetic resonance imaging in patients recently recovered from coronavirus disease 2019 (COVID-19). *JAMA Cardiol*. 2020;5(11):1265–1273. DOI:10.1001/jamacardio.2020.3557.
4. Kuck, KH. Arrhythmias and sudden cardiac death in the COVID-19 pandemic. *Herz*. 2020;45:325–326. DOI:10.1007/s00059-020-04924-0.
5. American College of Cardiology. 2020. Clinical guidance for the CV care team. <https://www.acc.org/~media/665AFA1E710B4B3293138D14BE8D1213.pdf>. Accessed August 24, 2021.

Philips Medical Systems
22100 Bothell Everett Highway
Bothell, WA 98021-8431, USA

Philips Medizin Systeme Boeblingen GmbH
Hewlett-Packard-Strasse 2
71034 Boeblingen, Germany



© 2021 Koninklijke Philips N.V. All rights are reserved. Philips reserves the right to make changes in specifications and/or to discontinue any product at any time without notice or obligation and will not be liable for any consequences resulting from the use of this publication. Trademarks are the property of Koninklijke Philips N.V. or their respective owners.



www.philips.com

Printed in the Netherlands.
4522 991 65331 * SEP 2021