

PHILIPS

AVENT

Bottom plate

Sterilizer

CP1232



Bottom plate for milk drip tray

Helps preventing a burning smell

The bottom plate of the milk drip tray directs any residual milk away from the heating plate, preventing a burning smell and staining of the heating plate.

Specifications

Replaceable part

Fits Product type: SCF291, SCF293

