


Philips Avent
Bottom plate

Steriliser

CP1232



Bottom plate for milk drip tray

Helps prevent a burning smell

The bottom plate of the milk drip tray directs any residual milk away from the heating plate, preventing a burning smell and any staining of the heating plate.

Specifications

Replaceable part

- Fits product types:: SCF291, SCF293



Issue date 2023-10-06

Version: 2.2.1

© 2023 Koninklijke Philips N.V.
All Rights reserved.

Specifications are subject to change without notice.
Trademarks are the property of Koninklijke Philips N.V.
or their respective owners.

www.philips.com