



Philips Performer  
Replacement Kit

4 x dust bags (s-bag® ULP)

1 x Allergy H13 exhaust filter  
1 x triple-layer motor filter

FC8060/01

## Replacement kit for Performer Pro/Expert/Ultimate

### Original dust bags and filter replacements

Original starter kit for the Philips vacuum cleaners. The kit contains 4 dust bags, together with the motor and exhaust filters which need to be replaced once a year.

#### Philips Original accessories

- Allergy H13 exhaust filter for excellent filtration
- s-bag® Ultra Long Performance original dust bags
- Triple-layer motor filter

# PHILIPS

Replacement Kit  
4 x dust bags (s-bag® ULP) 1 x Allergy H13 exhaust filter, 1 x triple-layer motor filter

## Specifications

### Contains

- s-bag Ultra Long Performance: 4x
- HEPA filter: 1x
- Triple-layer inlet filter: 1x

### Suitable for

- Jewel: FC9050 - FC9079

- Performer: FC8680 - FC8682, FC9150 - FC9179
- Performer Expert: FC8720 - FC8728
- PerformerPro: FC9180 - FC9199
- Performer Ultimate: FC8921 - FC8925, FC8941 - FC8957
- 7000 Series, Performer Silent: FC8741, FC8743, FC8745, FC8779 - FC8786

FC8060/01


## Highlights

### s-bag® Ultra Long Performance



The kit contains 4 x s-bag® Ultra Long Performance original dust bags. This dust bag has an XXL 5 liter capacity and therefore it helps maintain the cleaning performance for longer. Made of premium, multilayer, non-clogging material, the s-bag Ultra Long Performance guarantees excellent suction power and filtration, lasting up to 80% longer than the standard bag.

### Allergy H13 exhaust filter



The kit contains 1 x Allergy H13 exhaust filter. The Allergy H13 filter captures more than 99.95% of fine dust, which other filters simply recirculate back into the air of your home. It traps the fine particles, such as pollens and dust mites, which trigger allergy and asthma symptoms. The filter should be replaced once a year.

### Triple-layer motor filter



The kit contains 1 x triple-layer motor filter. This filter prevents fine dust from reaching the motor and damaging it. The filter should be replaced once a year.



Issue date 2022-06-20

Version: 4.4.3

EAN: 08 71010 36253 15

© 2022 Koninklijke Philips N.V.  
All Rights reserved.

Specifications are subject to change without notice.  
Trademarks are the property of Koninklijke Philips N.V.  
or their respective owners.

[www.philips.com](http://www.philips.com)