



Philips
exhaust filter

1 HEPA10 filter

Excellent filtration
Replace every 6 months
Compatible with FC8130...39

FC8070/01

Optimal filtration

HEPA exhaust filter for Philips vacuum cleaner

This Philips HEPA filter FC8070/01 catches harmful microscopic vermin that causes respiratory allergies. To maintain effective filtration the filter of your vacuum cleaner should be replaced every 6 months.

Perfect fit

- Original Philips exhaust filter

Optimal filtration

- EPA 10 filter captures all dust

PHILIPS

exhaust filter

1 HEPA10 filter Excellent filtration, Replace every 6 months, Compatible with FC8130...39

Specifications

Accessory specifications

- Number of exhaust filters: 1

- Replacement filter for: FC8130 - FC8149

FC8070/01

Highlights

Philips exhaust filter



Original Philips exhaust filter

EPA 10 filter



EPA 10 filter captures all dust



Issue date 2023-04-14

Version: 2.2.1

© 2023 Koninklijke Philips N.V.
All Rights reserved.

Specifications are subject to change without notice.
Trademarks are the property of Koninklijke Philips N.V.
or their respective owners.

www.philips.com