

A USB cable to charge your device

Check for compatibility below

A USB cable to conveniently charge your device via USB ports. Compatible with only USB charged devices

Ease of using Philips spare parts

• Easily renew your product with original Philips parts

USB Cable CP1788/01

Highlights

Easy replacement of product parts

From time to time your product needs a facelift, and with Philips consumer replacement parts to renew your product, it's never been so easy! All this with guaranteed Philips quality.

Issue date 2025-09-10 Version: 22.22.1

Specifications are subject to change without notice. Trademarks are the property of Koninklijke Philips N.V. or their respective owners.

© 2025 Koninklijke Philips N.V.

All Rights reserved.



Specifications

Replaceable parts

Fit product types: BG3007, BG3017, BG3027, BG3480, BG5021, BG5470, BG7485, BRL126, BRL136, BRL146, BRL166, BT3233, BT3234, BT3238, BT3239, BT3615, BT3617, BT3620, BT3625, BT3660, BT3665, BT5775, BT5780, BT7665, BT7670, MG3915, MG3920, MG3930, MG3940, MG3945, MG3946, MG5920, MG5930, MG5940, MG5950, MG7920, MG7925, MG7930, MG7940, MG7950, MG9530, MG9540, MG9550, MG9552, MG9553, MG9555, QP1324, QP1324, QP1424, QP1424, QP1924, QP2724, QP2734, QP2824 QP2834, QP4530, QP4630, QP4631, QP6506, QP6507, QP6542, QP6552, QP6652, \$1134, \$1141, \$1142, \$3143, \$3144, \$3145, \$3241, \$3242, \$3243, \$3244, \$3341, \$3342, \$3343, \$3344, \$5880, \$5883, \$5884, \$5885, \$5886, \$5887, \$5889, \$5898, \$7882, \$7885, \$7886, \$7887, \$8692, \$8696, \$8697, X3001, X3002, X3003, X3021, X3051, X3052, X3053, X3063, X5001, X5002, X5003, X5004, X5005, X5006, X5007, X5009, X5012, X5052, X5053, X5063, X5102, XP521, XP524, XQ5225, XQ523, XU5235, XU525, BT3619, BT5765, BT5785, BT7660, QP6532, S1151, X9000, X9001, X9002, X9003, XP9200, XP9201, XP9202, XP9203, XP9204, XP9205, XP9207, XP9208, XP9400, XP9401, XP9402, XP9403, XP9404, XP9405, QP401