

进口受影响彩色超声诊断系统序列号和3D9-3v机械容积探头序列号：

序号	彩色超声诊断系统型号	彩色超声诊断系统序列号	3D9-3v机械容积探头序列号
1	EPIQ 5	US123C1518	F09BTC
2	EPIQ 5	US423C0647	F0B7NN
3	EPIQ 5	US523C2291	F0BXT4
4	EPIQ 5	US120C1991	B3HLN6
5	EPIQ 5	US316C0552	F09YQ6
6	EPIQ 5W	US423C0711	F0B95G
7	EPIQ 5W	US323C1892	F0B7XC
8	EPIQ 5W	US423C0150	F0B6K9
9	EPIQ 7	US223B0149	F09F42
10	EPIQ 7	US423B0083	F0BBGX
11	EPIQ 7	US323B0677	F09V2J
12	EPIQ 7	US516B0089	B32MKY
13	EPIQ 7	US621B2087	B2ZR05
14	EPIQ 7	US621B2087	B32MK3
15	EPIQ 7	US323B2089	B25331
16	EPIQ 7	US423B1863	B3LDH7
17	EPIQ 7W	US223B0070	F09JT0
18	EPIQ 7W	US223B0069	F09F45
19	EPIQ 7W	US323B0880	F0B6KG
20	EPIQ 7W	US523B0471	F0BJB1
21	EPIQ 7W	US922B0673	B2JFNX
22	EPIQ Elite	US423B1574	F0BHWT
23	EPIQ Elite	US123B1876	F09F43
24	EPIQ Elite	US123B2113	F08X01
25	EPIQ Elite	US523B0177	F0BR78
26	EPIQ Elite	US423B1038	F0BFKC
27	EPIQ Elite	US423B1813	F0BMC1
28	EPIQ Elite	US423B1805	F0BJYR
29	EPIQ Elite	US423B0909	F0BFXK
30	Affiniti 70	US518F1423	B2JDYH
31	Affiniti 70	US518F1423	B2RL1T

国产受影响彩色超声诊断系统序列号和3D9-3v机械容积探头序列号：

序号	彩色超声诊断系统型号	彩色超声诊断系统序列号	3D9-3v机械容积探头序列号
1	Affiniti 30	SZ821E1598	B0T4K4
2	EPIQ 5	SZ323C1990	F0B7XF
3	EPIQ 5W	SZN22C1549	F07XRX
4	EPIQ 5W	SZN22C2661	F04DXD
5	EPIQ 5W	SZ223C0956	F01ZG6
6	EPIQ 5W	SZ323C0705	F0B7NZ
7	EPIQ 7 Plus	SZ223B1791	F09NLR
8	EPIQ 7W EXP	SZ223B1078	F01ZZ5
9	EPIQ 7W Plus	SZ022B0645	F04F2L

10	EPIQ 7W	SZN22B2898	F04F29
11	EPIQ 7W	SZD22B0911	F04F2G
12	EPIQ 7W	SZD22B0347	F04F2H
13	EPIQ 7W	SZD22B0348	F03Q35
14	EPIQ 7W	SZ123B1041	F07XRT
15	EPIQ 7W	SZ123B1042	F07XRV
16	EPIQ 7W	SZ123B1191	F07Y4Q
17	EPIQ 7W	SZ123B1040	F04DX8
18	EPIQ 7W	SZ223B0986	B3TBRW
19	EPIQ 7W	SZ223B0991	F01W12
20	EPIQ 7W	SZ223B1429	F024G2
21	EPIQ 7W	SZD22B1915	F09MHD
22	EPIQ 7W	SZ323B0689	F0B7P1